



STENCILMATE[™] USER INSTRUCTIONS




STEP 2


Place the part StencilMate [™] aligning it with part lands and applying pressure to the stencil. Squeegee solder paste with a manual squeegee into the apertures. Clean off surface of stencil.




STEP 1 Remove device from PCB. Wick or scavenge and clean part.



STEP 3 Reflow paste based on solder manufacturer's profile.



STEP 4 Remove StencillMate[™] from device clean and inspect.



STEP 5

Inspect to make sure the "bumps" are uniform and consistent on all of the pads.

